

Our new dry steam cleaning service, effectively cleans hard to reach areas of the bellmouth, turbine rotor, dovetails and shell casings to remove difficult fixed contaminants. Dry steam cleaning improves surface smoothness for eddy current inspections and make assembly easier, while providing EHS benefits.

Outcomes:

- Cleans dove-tails in 6-8 hours to efficiently schedule eddy current exams
- Cleans rotor, upper and lower shell casings in 22 hours
- · Effective for Bellmouth and In-situ (Rotor-in) cleaning
- Increases surface smoothness by 40%
- Minimizes EHS waste little to no water collection and no cleaning chemicals required





Contact Us: 1-800-979-2497

